Doc. TRR-01 LINE 20

## TRUCK REPAIR RECORD

| Concrete Pump Owner: SIG PUMPS PTY                       | LIU  |
|--|--|
| Truck Model: ISUZU                                       | Make: POWERCRETE                                   |
| Truck Rego No: CH 91 TI                                  | Year of Manufacture: 2004                          |
| Model and Type of Boom: HIGH PRESSUR                     | E LINE PUMP  |
| Work Cover Registration Number: N/A                      |  |
|  |  |
| RECORDS OF REPAIRS CARRIED OUT:                          |  |
| Friday 03.03.2023  |  |
| Visual inspection of all fluids. Engine oil, coolant, hy | vdraulic oil.                                      |
| Took machine to GB Auto Electrical. They fitted sta      |  |
| Visual inspection of water box. Drained and cleaned      | d water box. Replaced water                        |
| Visual inspection of all emergency stops.                |  |
| Visual inspection of all lights and globes. Visual insp  | pection of wiper blades                            |
| Inspection of hopper grill. Ok and Operational. Vis      | ual inspection of all tyres, treads and side walls |
| Started and run motor - OK.                              | MEDICASSOC   |
| Passed and ready for work                                |  |
|  |  |
|  |  |
|  |  |
|  |  |
|  |  |
|  |  |
|  |  |
|  |  |
|  |  |
|  |  |
|  |  |
| D IOE BASSII   |  |
| Responsible Person: JOE BASSIL                           |  |
| Sign:<br>Date: 03.03.2023                                |  |
| Date: 03.03.2023   |  |