## MILOP Design and Consulting Pty Ltd

Mechanical and steel structure engineering, design & consulting. Concrete pumping equipment, tower cranes, inspection and certification. Professional engineer

ABN: 91 104 582 050

PO Box 3345 Wetheril Park, NSW 2164 m: 0413 424 819, milop@tpg.com.au; www.milop.com.au

STG Pumps Pty Ltd Po Box 134 MOOREBANK, NSW, 1875

**Attn: Joe Bassil** 

RE: Concrete Boom Pump, Powercrete / Antonelli 46m,

**Inspection Report and Certification for Continued Service** 

Report no: 2765/23, 01st May 2023

The concrete boom pump Powercrete / Antonelli 48m was inspected on the 01st May 2023 in the Riverstone Rd, Moorebank.

The concrete boom pump was inspected in assembly conditions. The boom and outriggers were opened and the boom arms unfolded.

The inspection is a regular periodic boom pumps inspection, as required by AS 2550.15 – Concrete Placing Equipment, and it presents an assessment of structural conditions for continued service of the plant at the time of the inspection.

The concrete boom pump's technical specifications:

Boom and pump manufacturer: Antonelli / Powercrete Model and size: M45/6Z/125-BT46

Boom / pump serial number: MA0074
Hydraulic operating pressure 350 bar
Concrete piping ND 125mm
Hydraulic pressure boom / pump 370 bar / 300 bar

Max concrete pressure110 barWorking hours3666 hrYear of manufacture:2017End hose4 mTruck Volvo FM12 rego platesAZ20TV

The concrete boom pump has received a periodic inspection in accordance with the criteria in AS 2550.15:2019, Clause 6.4.

Details of the periodic inspection are enclosed.

Following AS 2550.15:2019, the next inspection is recommended after 500 operating hours or before the  $101^{st}$  of May 2024.

01st May 2023

Inspected by:

Michael Podinic, BScME, MIEAust\*

<sup>\*)</sup> Michael Podinic, professional engineer, member of Engineers Australia, no 1047610, more than 30 years experience in development, design, analysis, certification and verification of construction machinery, concrete pumping equipment and other mechanical machinery, www.milop.com.au

STG Pumps Pty Ltd, Concrete boom pump Antonelli M45/6Z, Yearly Inspection, Certificate report no: 2765/23, 01st May 2023

## **PERIODIC INSPECTION REPORT - Details**

Pump details	_		
Manufacturer / Model POWERCRETE / T 130-203-2400	Serial	number STG.2EP180.02	Year of manufacture 2009
Maximum hydraulic system pressure 300 bar		Maximum concrete del Rod side 115 bar	livery pressure

Boom details		
Boom manufacturer / model M45/6Z/125-BT46	Boom serial number MA0074	YOM of the boom 2017
Type of boom Truck mounted, six stages M45/41/6/125	Max horizontal reach (from the centre of slew ring) 41 m	Max rated working pressure of the pipes 85 bar
Max pipe diameter 125 mm (5")		Operating pump hours
Max drop hose diameter 125mm (4")	Max drop hose length 4m	Total 3666 hr

Carrier information (Truck)				
Carrier manufacturer VOLVO FM MK2	Rego plate AZ 20TV			

Date 01st May 2023

No. of defects and safe to use None

Stop operation until defects

are addressed No No Reinspection required

Inspected:

Michael Podinic, BScME, MIEAust Wodunt

m. 0413 424 819. milop@tpg.com.au www.milop.com.au



STG Pumps Pty Ltd, Concrete boom pump Antonelli M45/6Z, Yearly Inspection, Certificate report no: 2765/23, 01st May 2023

## **PERIODIC INSPECTION REPORT – Details** (In accordance

with AS 2550.15:2019)

Owner/Controller details			
Owner/Controller of the concrete equipment: STG Pumps Pty Ltd			
Location of inspection	Riverside Rd, Chipping Norton		
Names of people involved in the inspection	Joe		

Fault code

00	No objections	08	Corrosion	16	Porous	24	Deformation
01	Cracks	09	Damaged paint	17	Burnt out	25	Bearing clearance
02	Broken	10	Worn through	18	Loose	26	Lubrication
03	Leaking	11	Scored	19	Jammed	27	Legibility
04	No function	12	Bent	20	Judders	28	Parts missing
05	Short life	13	Noise	21	Soiled	29	Hydraulic
06	Wear	14	Vibration	22	Loose contact	30	Electrical
07	Chips	15	Others	23	Temperature	31	Re-inspection required
A1	Not available	A2	Inadequate information				

Item	Description	Fault code	Method of inspection	Acceptance criterion	Observation	Stat us	Phot os (Y/N ) Rem
100	Machine docum	ients					
	Instruction handbook		Visual	Exist		Ok	N
	Spare-parts list		Visual	Exist		Ok	N
200	Support structure		Visual	No faults	No objection	Ok	N
	Frame attachment		Visual	No faults	No objection	Ok	N
300	Front outriggers R + L						
	Transport lock		Visual	Automatic device lock	No objection	Ok	N
	Outriggers		Visual	No crack, no corrosion distortion	No objection	Ok	N
	Extension box 1		Visual	No crack, no corrosion	No objection	Ok	N
	Extension lock		Visual	Automatic	No objection	Ok	N
	Pivot bearing		Visual	Automatic	No objection	Ok	N
	Pivot safeguard		Visual	Automatic	No objection	Ok	N
	Outrigger safeguard		Visual	No faults	No objection	Ok	N
	Outrigger lock		Visual	Functional locking device	No objection	Ok	N
	Outrigger cylinder attachment		Visual	No faults	No Objection	Ok	N
	Outrigger cylinder		Visual	No faults	No objection	Ok	N
	Pivot cylinder		Visual	No faults	No objection	Ok	N
	Extension hydraulics		Visual	No leak	No objection	Ok	N
	Pressure setting		Visual	Factory setting	No objection	Ok	N
400	Rear outriggers R+L						

MILOP Design and Consulting Pty Ltd Pag STG Pumps Pty Ltd, Concrete boom pump Antonelli M45/6Z, Yearly Inspection, Certificate report no: 2765/23, 01st May 2023

	Transport lock	Visual	Automatic device lock	No objection	Ok	N
	Outriggers		No crack, no corrosion distortion		Ok	N
	Extension box 1	Visual Visual	No crack, no corrosion  No crack, no corrosion	No objection  No objection	Ok	N
	Extension lock	Visual	Automatic	No objection	Ok	N
	Pivot bearing	Visual	Automatic	No objection	Ok	N
	Pivot safeguard	Visual	Automatic	No objection	Ok	N
	Outrigger safeguard	Visual	No faults	No objection	Ok	N
	Outrigger lock	Visual	Functional locking device	No objection	Ok	N
	Outrigger cylinder attachment	Visual	No faults	No Objection	Ok	N
	Outrigger cylinder	Visual	No faults	No objection	Ok	N
	Pivot cylinder	Visual	No faults	No objection	Ok	N
	Extension hydraulics	Visual	No leak	No objection	Ok	N
	Pressure setting	Visual	Factory setting	No objection	Ok	N
Remark	-	Visuai	ractory setting	No objection	OK	11
500	Concrete-placing boom pedestal (c	ommon)				
	Concrete-placing boom pedestal	Visual	No faults	No objection	Ok	N
	Superstructure frame	Visual	No faults	No objection	Ok	N
	Chassis frame	Visual	No faults	No objection	Ok	N
	Concrete-placing boom support	Visual	No faults	No objection	Ok	N
	Transport locks and seats	Visual	No faults  No faults	No objection	Ok	N
	Hydraulic line	Visual	No faults  No faults	No objection	Ok	N
600	Slewing head with ball pivot conne		No faults	No objection	OK	11
	Slewing head	Visual	No faults	No objection	Ok	N
	Ball-mounted slewing ring	Visual,	Max play 1.5 mm	No objection	Ok	N
	Ball-mounted slewing ring	Visual	All bolts tightened	No objection	Ok	N
	Drive pinion	Visual	No faults	No objection	Ok	N
	Slewing drive attachment	Visual	No faults	No objection	Ok	N
	Slewing limitation	Visual	Slewing limited by switche	No objection	Ok	N
	Slewing drive (gearing clearance)	Visual	1.1 mm	No objection	Ok	N
	Slewing drive			No objection	Ok	N
	Brake function	Visual	No faults	No objection	Ok	N
	Speed	Visual	No faults	No objection	Ok	N
	-	Measuring	1 rev/ 2.5 min			
	Pressure setting Hydraulic lines	Visual	Factory Setting	No objection  No objection	Ok Ok	N
D 1		Visual	No faults	140 objection	OK	N
Remarks	Concrete-placing boom					
	Arm 1	X 7' 1	N. C. 1	NT 1 * · · ·	01	3.7
040	Guide and rest of the arm	Visual	No faults	No objection	Ok	N
810	Delivery-line support	Visual	No faults	No objection	Ok	N
		Visual	No faults	No objection	Ok	N
	Arm 2	Visual	No faults	No objection	Ok	N
820	Guide and rest of the arm	Visual	No faults	No objection	Ok	N
	Delivery-line support	Visual	No faults	No objection	Ok	N
830	Arm 3	Visual	No faults	No objection	Ok	N
	Guide and rest of the arm	Visual	No faults	No objection	Ok	N
	Delivery-line support	Visual	No faults	No objection	Ok	N
840	Arm 4	Visual	No faults	No objection	Ok	N

STG Pumps Pty Ltd, Concrete boom pump Antonelli M45/6Z, Yearly Inspection, Certificate report no: 2765/23, 01st May 2023

	Guide and rest of the arm	Visual	No faults	No objection	Ok	N
	Delivery-line support	Visual	No faults	No objection	Ok	N
	Arm 5	<del>                                     </del>		_	Ok	
	Guide and rest of the arm	Visual	No faults	No objection		N
850		Visual	No faults	No objection	Ok	N
0.60	Delivery-line support	Visual	No faults	No objection	Ok	N
860	Arm 6 Guide and rest of the arm	Visual	No faults	No objection	OK OK	N N
	Delivery-line support	Visual	No faults	No objection		N
	Denvery-line support	Visual	No faults	No objection	OK	11
Remar						
900	Joint 'A'-Arm 1 - Turret					
	Joint Pin/Bushes/Linkage	Visual	No cracks, wear < 0.8 mm	wear 0.52 mm	Ok	N
	Cylinder 1- Turret – Arm1	Visual	No faults	No objection	ok	N
	Pressure setting		Factory setting			
	Hydraulic lines	Visual	No faults	No objection	Ok	N
	Safety valves: piston/rod side	Visual	No faults	No objection	Ok	N
1000	Joint 'B'—Arm 1–2					
	Joint Pin/Bushes/Linkage	Visual	Cracks, wear < 0.8mm	No cracks, wear 0.62	Ok	N
	Cylinder B	Visual	No faults	No objection	Ok	N
	Speed	Visual	Depend on engine revs	Variable	Ok	N
	Pressure setting		Factory setting			
	Hydraulic lines	Visual	No faults	No objection	Ok	N
	Safety valves: piston/rod side	Visual	No faults	No objection	Ok	N
Remark	CS:	1 1	- 10 - 200-200			
1100	Joint 'C'—Arm 2 - 3					
	Forcing lever	Visual	No faults	No objection	Ok	N
	Pressure rod	Visual	No faults	No objection	Ok	N
	Joint Pin/Bushes/Linkage	Visual	Wear < 0.7mm	wear 0.52mm	Ok	N
	Cylinder C	Visual	No faults	No objection	Ok	N
	Speed	Visual	Depend on engine revs	Variable	Ok	N
	Pressure setting		Factory setting			
	Hydraulic lines	Visual	No faults	No objection	Ok	N
	Safety valves: piston/rod side	Visual	No faults	No objection	Ok	N
1200	Joint 'D'—Arm 3 - 4					
	Forcing lever	Visual	No faults	No objection	Ok	N
	Pressure rod	Visual	No faults	No objection	Ok	N
	Joint bolt	Visual	Cracks, wear < 0.60mm	wear 0.43mm	Ok	N
	Cylinder D	Visual	No leak, no cracks	No objection	Ok	N
	Speed	Visual	Depend on engine revs	Variable	Ok	N
	Pressure setting		Factory setting			
	Hydraulic lines	Visual	No leak, no damage	No objection	Ok	N
	Safety valves: piston/rod side	Visual	No faults	No objection	Ok	N
1300	Joint 'E'—Arm 4 - 5	X7:1	No faults	No objection	O1-	N.T
	Forcing lever	Visual	No faults	No objection	Ok	N
	Pressure rod	Visual	No faults	No objection	Ok	N
	Joint, Pins/Bushes/Linkages	Visual	Cracks, wear < 0.60mm	wear 0.52mm	Ok	N
	Cylinder E	Visual	No leak, no cracks	No objection	Ok	
	Speed	Visual	Depend on engine revs	Variable	Ok	
	Pressure setting		Factory setting			

MILOP Design and Consulting Pty Ltd Pag STG Pumps Pty Ltd, Concrete boom pump Antonelli M45/6Z, Yearly Inspection, Certificate report no: 2765/23, 01st May 2023

1	Hydraulic lines	Visual	No leak, no damage	No objection	Ok	
	Safety valves: piston/rod side	Visual		No objection	Ok	N
	Joint 'F'—Arm 5 - 6	7 10 0 0 0	110 14010	Tio dejetion	-	- '
	Forcing lever	Visual	No faults	No objection	Ok	N
	Pressure rod	Visual	No faults	No objection	Ok	N
	Joint, Pins/Bushes/Linkages	Visual	Cracks, wear < 0.60mm	wear 0.55mm	Ok	N
	Cylinder F	Visual	No leak, no cracks	No objection	Ok	N
	Speed	Visual	Depend on engine revs	Variable	Ok	N
	Pressure setting		Factory setting			
	Hydraulic lines	Visual	, ,	No objection	Ok	N
1400	Concrete-delivery line		, ,	<u> </u>		
	Fitted delivery line: DN 125 mm	Visual	Max concrete pressure 85bar	No faults	Ok	N
	End hose DN and length	Visual	5" (125mm), length 4 m	No faults	Ok	N
	Remaining line wall thickness adequate	Visual	Min thickness 2 mm	No objection	OK	N
	Alignment of delivery line and	Visual		No Objection	Ok	N
	pivot points					
	Coupling safety pins	Visual	to be installed	All installed	Ok	N
	End hose safety sling/chain tighten	Visual	•	All installed	OK	N
Remark	End hose connector	Visual	Safely attached to end	Safe attached	OK	N
1500	Hydraulics, control and hydraulic	rolros				
1500	Pressure relief valves	Visual	Fastama asttina	No leelee	Ola	NT
	Pressure setting	Visual	Factory setting Factory setting	No leaks No leaks	Ok OK	N N
	Hydraulic lines	Visual	No faults		Ok	N
	Manual operation (switching function)	visuai		No Objection	Ok	N
	Concrete-placing boom control block	Visual	from control valve levers returning in a neutral	No Objection	OK	N
	Hydraulic pumps	Visual	No leaks	No objection  No objection	Ok	N
1600	Electrical system	Visuai	140 leaks	No objection	OK	N
	Remote control (switching function)	Visual	to be functional	No objection	Ok	N
	Emergency-stops function	Visual,	Cut off the boom and pump movemen	•	Ok	N
	Electrical selector switch for concrete-placing boom function	Visual, check	Switch functional	In function	OK	N
	Electrical cable harnesses	Visual	cable to be harnessed	No objection	OK	N
1700	Warning and Safety signs	V IS GELL	<b>4</b> 010 to 00 11411100000	110 00   00 10 10 11	011	- '
	Warning signs	Visual	to be affixed and legible	Installed	OK	N
	Information signs	Visual t	o be affixed and legible	Installed	OK	N
	Operational information signs	Visual t	o be affixed and legible	Installed	OK	N
	Operating instructions signs	Visual t	o be affixed and legible	Installed	OK	N
	Use as crane prohibited signs	Visual t	o be affixed and legible	Installed	OK	N
	Rating signs	Visual t	o be affixed and legible	Installed	OK	N
	High-voltage warning signs	Visual t	o be affixed and legible	Installed	OK	N
2000	Machine documents					
	Instruction handbook	Visual	to be in the truck	In truck	OK	N
	Spare-parts list	Visual	to be in the office	In-office	OK	N
2001	Drive unit					
	Coupling and flange	Visual	Firm flange connection	No objection	OK	N
2200	Gear unit	Visual	Hydraulic motor installed	No objection	OK	N
2300	Hydraulic pumps	Visual	No oil leak, firmly attached	No objection	OK	N
2400	Oil tank	Visual	No oil leak	No objection	Ok	N
2500	Fuel system	1	No leaks, damage	No objection	Ok	N

MILOP Design and Consulting Pty Ltd Pag STG Pumps Pty Ltd, Concrete boom pump Antonelli M45/6Z, Yearly Inspection, Certificate report no: 2765/23, 01st May 2023

2600	Drive shaft		No faults	No damage	Ok	N
2700	Hydraulic control			-		
	Pressure relief valve	Visual	Factory setting			
	Pressure setting	Visual	No faults	No objection	OK	N
	Hydraulic lines	Visual	No faults	Ok	OK	N
	Manual operation	Visual	Operation from control valve	No objection	OK	N
2800	Oil cooler	Visual	No faults	No objection	OK	N
2900	Accumulator					
	Proof of prescribed tests according to pressure vessel regulations		Installed, Factory tested	No objection	OK	N
	Pressure gauge	Visual	Pressure gauge for accumulator	No objection	OK	N
Remar	·ks					
3100	Hydraulic motor	Visual	oil cooler, remix hopper shaft, water pun	No objection	OK	N
3200	Hydraulic line	Visual	No leak, no damage	No objection	OK	N
3400	Switch cabinet	Visual	Protected, no oil leak	No objection	OK	N
3700	S-transfer tube	Visual	shaft lubricated, gap of wear plates and cutting ring allowable	No objection	OK	N
3800	Concrete hopper	I	,			
	Concrete paddles	Visual	100mm from hopper grate	No objection	OK	N
Remarks		, 150001	roomm nom nopper grade	Tio objection	011	
4200	Water tank	Visual	Incorporated in deck	No objection	OK	N
4300	Chassis	Visual	No cracks, corrosion	No objection	OK	N
4400	Flushing water pump	Visual	Firmly attached, no oil or water leaks	No objection	OK	N
4500	Vibrator	Visual	attached to the grate	No objection	OK	N
4600	Other protective devices		9	J		
	Steps	Visual	No faults	No objection	OK	N
	Non-slip surface of steps	Visual	Non- slip surface	No objection	OK	N
	Safety rail	Visual	Safe walking on the deck	No objection	OK	N
	Hinged grill-type guard on hopper	Visual	safe fixed when is opened	No objection	OK	N
	Distance between grill bars	Visual	Max 50 mm	Visual	OK	N
	Distance between grill and crushing poi	Visual	Min 100 mm	Visual	OK	N
	Hinged grill-type guard	Visual	No faults	Visual	OK	N
	Concrete paddles stopped on opening grate	Visual	Switch off valve installed to stop remixing shaft	Installed	OK	N
	Transfer tube stopped on opening of movable grill-type guard	Visual	stopped on opening of grate	It stops	OK	N
	Safeguard to prevent movable grill- type guard from falling	Visual		Installed	OK	N
	Cleaning-access closure of hopper	Visual	Access to hopper cleaning	No Objection	OK	N
	Valve-switching cylinder covered	Visual	Change over cylinder covered	In design	OK	N
	All parts with burning/ scalding hazard covered, e.g. exhaust	Visual	Protection from burning and hot surfaces	No objection	Ok	N
4700	Electrical equipment					
	Functioning of control elements	Visual	Control elements to be functional	All works	Ok	N
	Emergency-stop device	Visual	Should cut of all movement	All works	OK	N
	Temperature sensor	Visual	Oil temperature sensor	Installed	Ok	N

## **Notes and remarks**

No notes